

We recently discovered an issue with Pcommserver.exe which causes the following problems:

- 1) Ethernet communication will not work with PMAC-NC Pro2 (Runtime or Designer).
- 2) Random CNC program crashing regardless of communication format.

This issue affects **PMAC-NC Pro2** products only. Pcommserver builds between **12/21/06 and 04/13/07** are affected. Please check the date of the Pcommserver.exe to determine if you are affected.

The Pcommserver.exe is located in the following Windows folder:  
C:\WINDOWS\system32\PcommServer.exe.

If you or your customers are experiencing any of these symptoms contact myself or anyone in Technical Support for assistance.

The latest versions of PMAC-NC Pro2 Runtime and PMAC-NC Pro2 Designer are available for download from the web-site.