



# Power PMAC Patch (Release Notes)s

Version (2.2.1.x) January 24, 2017 Patch

**\*NOTE: (2.2.1.x) Patch will not work unless Power PMAC IDE (2.2.0.39) or later is already installed. \***

## New Features:

- New Identification/Error Color scheme for Status Window.
- Download from Component Library.
- Updated EC Engineer from version 2.4.3 to version 2.5.6

## Bug Fixes:

- [Bugzilla ID: 1498](#), Download from Component Library.
- [Bugzilla ID: 1468](#), Fixed opening and plotting a saved configuration file with data (.prj) error.
- [Bugzilla ID: 1478](#), Throws Instructional message for Hardware mismatch on devices connected using Acontis Stack.
- [Bugzilla ID: 1485](#), Fixed Acontis Stack download ENI file error when using System Setup.
- [Bugzilla ID: 1504](#), EtherCAT Device Startup Tab error fixed.
- [Bugzilla ID: 1505](#), Error adding a Dictionary Object message clarified.
- [Bugzilla ID: 1522](#), Coordinate System and Macro Tabs now update within the Status Window.
- [Bugzilla ID: 1470](#), Improved Status Window Identification/Error Colors.
- [Bugzilla ID: 1501](#), Uploading of the Acontis log files.
- [Bugzilla ID: 1502](#), Added lib math to the make files to fix IPC project compilation issues.
- [Bugzilla ID: 1511](#), Fixed usralgo.ko compilation issues with LX86 and ARM machines.
- [Bugzilla ID: 1524](#), Fixed the graphical display issue in the Task Manager window on uPowerPMAC.

